

5091 WOMEN'S SEAPORT FULL ZIP HOODIE

SIZES XXS-3XL

- :: 81% polyester/15% Rayon/4% Spandex double knit (8.11 oz/yd²)
- :: Full zip styling for easy on/off and a three piece hood for coverage against the weather

Hood with adjustable drawstrings

Color block styling with accent welding

Cflex™ fabric

Full zip styling

Open patch pockets

BACK VIEW



COMFORT & CONVENIENCE

- :: Made from our high-performance Cflex™ fabric that has 4-way stretch construction for greater range of motion
- :: Full-zip styling for easy on/off and patch pockets to keep your valuables close and safe
- :: Features a three-piece hood with drawstrings for coverage against the weather and drop tail hem for added coverage
- :: Color block styling, accent black welding for Black/Grey and Grey/Black and grey welding on Navy/Grey

FABRIC

Cflex™ - 81% polyester/15% Rayon/4% Spandex double knit (8.11 oz/yd2)

SIZES

Sizes XXS-3XL

COLORS

006 Black/Grey, 002 Grey/Black, 096 Navy/Grey

GARMENT CARE

For better results turn inside out. Machine wash cold with like colors. Gentle Cycle. Do not bleach. Tumble dry low. Do not iron. Do not use fabric softeners.

DECORATION RECOMMENDATIONS

Embroidery: Ballpoint 75/10 needle. Two Tearaway backings, stacked and rotated into a multi-point star. No topical solvent needed.

Heat Transfer: Max temperature is 425 degrees Fahrenheit

Screen Printing: Automatic screen printing process with a dryer temperature of 350 degrees Fahrenheit. Maximum number of colors recommended is 4. Plastisol ink for both light and dark colors works best.

002
GREY/BLACK

006
BLACK/GREY

096
NAVY/GREY



SEAPORT FULL ZIP HOODIE WOMEN'S 5091	XXS	XS	S	M	L	XL	2XL	3XL	TOLERANCE
BODY LENGTH	26 ½	27	27 ½	28	28 ¾	29 ½	30	30 ½	½ +/-
ACROSS SHOULDER	14 ½	15	15 ½	16	16 ¾	17 ½	18 ¼	19	¾ +/-
CHEST WIDTH	17 ½	18 ½	19 ½	20 ½	22	23 ½	25 ½	27 ½	½ +/-
BOTTOM OPENING WIDTH	17	18	19	20	21 ½	23	25	27	½ +/-
SLEEVE LENGTH	31 ⅞	31 ¾	32 ¾	33	33 ¾	34 ½	35	35 ½	¼ +/-

KEY TO COMMONLY ABBREVIATED SPEC INFORMATION (ALL MEASUREMENTS ARE IN INCHES)

CB = CENTER BACK

CHEST 1 INCH DOWN = MEASURE THE FRONT OF THE GARMENT 1 INCH DOWN FROM THE ARMHOLE

1/2 = MEASURE ONLY THE FRONT OF THE GARMENT, THEN DOUBLE THAT MEASUREMENT TO GET THE TOTAL CIRCUMFERENCE

RELAXED = DO NOT STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, SIMPLY LEAVE THE ELASTIC RELAXED

STRETCHED = STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, MEASURE STRETCHED