

# 5087 WOMEN'S ADVENTURE JACKET

SIZES XXS-3XL

- :: 60% cotton/40% polyester French Terry knit blend  
(5.90 oz/yd<sup>2</sup>)
- :: Lightweight, transitional piece



Full zip styling

Rib knit trim on collar, cuffs and bottom band

Side Pockets with snap closure

BACK VIEW



**COMFORT & CONVENIENCE**

- :: Full zip styling
- :: Dyed-to-match rib knit trim design on collar, sleeve cuffs and bottom band
- :: Lightweight & transitional piece that is a great addition to any wardrobe

010 BLACK

**FABRIC**

60% cotton/40% polyester French Terry knit blend (5.90 oz/yd<sup>2</sup>)

**SIZES**

Sizes XXS-3XL

040 NAVY  
(AVAILABLE 1/15/20)

**COLORS**

010 Black, 220 Pewter Heather, 040 Navy (available 1/15/20)

**GARMENT CARE**

For better results turn inside out. Machine wash cold with like colors. Gentle Cycle. Only non-chlorine bleach when needed. Tumble dry low. Remove promptly. Cool iron if needed.

220 PEWTER  
HEATHER

**DECORATION RECOMMENDATIONS**

Embroidery: Ballpoint 75/10 needle. Two tearaway backings, stacked and rotated into a multipoint star. Do not use topical solvent. Most logos will require a laydown stitch behind to flatten material.

Heat Transfer: Maximum temperature recommended is 425°F

Screen Printing: Automatic screen printing process with a dryer temperature of 425 degrees Fahrenheit. Maximum number of colors recommended is 4. Plastisol ink for both light and dark colors works best. No catalyst needed.



ADVENTURE JACKET WOMEN'S 5087	XXS	XS	S	M	L	XL	2XL	3XL	TOLERANCE
BODY LENGTH	24 ½	25	25 ½	26	26 ¾	27 ½	28	28 ½	½ +/-
ACROSS SHOULDER	14	14 ½	15	15 ½	16 ¼	17	17 ¾	18 ½	¾ +/-
CHEST WIDTH	17 ½	18 ½	19 ½	20 ½	22	23 ½	25 ½	27 ½	½ +/-
BOTTOM OPENING WIDTH	17 ½	18 ½	19 ½	20 ½	22	23 ½	25 ½	27 ½	½ +/-
SLEEVE LENGTH	30 ¾	31 ¼	31 ¾	32 ½	33 ¼	34	34 ½	35	¼ +/-

**KEY TO COMMONLY ABBREVIATED SPEC INFORMATION (ALL MEASUREMENTS ARE IN INCHES)**

CB = CENTER BACK

CHEST 1 INCH DOWN = MEASURE THE FRONT OF THE GARMENT 1 INCH DOWN FROM THE ARMHOLE

1/2 = MEASURE ONLY THE FRONT OF THE GARMENT, THEN DOUBLE THAT MEASUREMENT TO GET THE TOTAL CIRCUMFERENCE

RELAXED = DO NOT STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, SIMPLY LEAVE THE ELASTIC RELAXED

STRETCHED = STRETCH THE GARMENT IF IT HAS ELASTIC TO MEASURE, MEASURE STRETCHED